







DUNAVOX JOY-65

DXJ-65.154DB



Front and rear plinth ventilation is needed.

